

Improve: Damp and fallen down overhead insulation in the crawlspace observed.

Recommend removing all insulation in the overhead floor joists, and if re-installing new insulation, covering the bottom of the floor joists containing the new insulation with plastic sheeting so it doesn't get damp and fall down again. Dampness in the crawlspace has led to the insulation falling down as well as current or past pest nesting in the insulation.