

Monitor: Moisture staining observed underneath the insulation on the roof decking. Trapped heat and moisture behind the insulation can lead to mold growth, roofing nail pops through the shingles, and a shortened shingle life. Consideration should be given to installing Styrofoam forms between the insulation and the roof decking.