

Improve: Poor ventilation observed in the attic: rusted roofing nails and/or roof decking condensation stains.

Recommend improving the ventilation which can reduce the chance of future mold growth in the attic and also help keep the home cooler in the summer and warmer in the winter, extend the life of the roof shingles, and reduce the chances of ice damming.