

Health Concern: Vermiculite insulation observed in the attic. Vermiculite should be assumed to contain Asbestos and so it should not be disturbed as that could potentially release asbestos fibers into the air. Recommend hiring a professional asbestos contractor if planning to remodel or conduct renovations that would disturb the vermiculite. See the EPA web site for more information:

<https://www.epa.gov/asbestos/protect-your-family-asbestos-contaminated-vermiculite-insulation>